



BLŪ
west











ASSEMBLY INSTRUCTION
81204.Z.02


PARTS LIST




Hardware:

A M6*35 mm  x14	B M15*10 mm  x14	C M5.8*30 mm  x10	D M4*35mm  x4	E M3.5*12 mm  x24
F  x4	G M4*14 mm  x20	H  x2	I M4*16mm  x2	J M4*35mm  x8
K  x4	(CL)  x2	(CR)  x2	(DL)  x2	(DR)  x2


STEP 1



A x 2



CR x 2




CL x 2



E x 12

STEP 2






B x 2








C x 2


STEP 3




STEP 4





STEP 5



STEP 6







STEP 7




STEP 8

X 2



STEP 9

X 2





B x 8

E x 12

DR x 2

DL x 2



STEP 10

